

CRUISING ALMANAC 2024

CUMULATIVE CORRECTIONS ISSUE 12.0

Cut-off date 30th July 2024

The Cruising Association, its officers, members, the editor and individual authors make no warranty as to the accuracy or reliability of any information contained in this publication and accept no liability for any loss, injury or damage occasioned to any person acting or refraining from action as a result of the use of such information or any decision made or action taken in reliance or partial reliance on it save that nothing contained in this publication in any way limits or excludes liability for negligence causing death or personal injury or for anything which may not legally be excluded or limited. No national hydrographic office, or local harbour authority has verified the information in these corrections, and none accept liability for the accuracy of reproduction or any modifications made thereafter therefore this product should not be used for navigation. New or amended Notices since the last Issue will be highlighted thus.

Please report any errors or omissions to <u>almanac@theca.org.uk</u>. Free monthly corrections by email are available by signing in at www.theca.org.uk/almanac/corrections.

General Information

p17 **SHIPPING FORECASTS ON RADIO 4,** Text **Amend** all except final sentence to:

- 00:48 Includes weather reports from coastal stations and an inshore waters forecast
- 05:20 Includes weather reports from coastal stations and an inshore waters forecast
- 17:54 Weekends Only

It will be broadcast on FM (BBC Radio 4), DAB and BBC Sounds. RE Apr24

England South Coast

p27 ISLES OF SCILLY St Mary's, Text

Col 4 line 19, **Insert,** A red floating sea water pipe has been established between 49°55'·65N 6°16'·60 W, near Dry Ledges, across the S edge of Pelistry Bay to the shore. It is supported by white buoys. Mariners navigational aids.

Local NM

p30 **NEWLYN,** Plan **Delete** Pierhead light F.R. in 50° 06′·16N 5° 32′·82W. NM 5032/23

p33 FALMOUTH HARBOUR, Plan

Eastern Breakwater E: **Insert** Y special purpose pillar Lt buoy Fl.Y.5s in 50°09'·33N 5°02'·55W ILNW 108/24

p34 **FALMOUTH**, Plan

Penryn River **Insert** pontoon joining 50°09'.96N 5°04'.84W 50°09'.94N 5°04'.69W. ILNW 483/22

p45 **BRIXHAM, Plan**

Insert: Minor R Lt in 50°24′·03N 3°30′·89W

Delete Lt Q.G in 50°23′·86N 3°30′·65W

Insert pontoon and minor G Lt joining: 50°23′·90N
3°30′·63W & 50°23′·87N 3°30′·63W

ILNW 131/24

p46 **TEIGNMOUTH HARBOUR,** Plan

Insert depth 1.1 in 50° 32′.37N 3° 29′.46W.

NM4180/22

p47 TEIGNMOUTH Text Col 3

Replace There is ... 265° by:

There is a dredged channel, (least depth 1·0m) marked by a Ldg line (Lucette Lt Oc.R.6s on the training wall on the left of the entrance with vertical W stripe on the sea wall or two vertical R lights) on 264°/084°.

p48 RIVER EXE, Plan

Insert depth, drying ht 0·6, and extend approximate 0m low water line SE to enclose, in 50° $36' \cdot 26N$ 3°24'·01W. NM 1822/24 Amend No 26 light-buoy from Fl.R.5s to Fl.R.10s, and position to 50° $40' \cdot 66N$ 3° $27' \cdot 92W$. NM 2279/24

p49 WEST BAY (BRIDPORT), Plan

Insert depth, 0·2 in 50° 42′·56N 2° 45′·84W.

Delete depth, 1·6 , close by.

NM 2002/24

p50 PORTLAND HARBOUR, Plan

Amend light-buoy to, Mo(A)8s in 50° 35′·20N 2° 27′·25W. NM 379/24

p52 **SWANAGE**, Plan

Latitude scale has been amended. For amended plan click here. ILNW Feb2024

p52 **APPROACHES to POOLE**, Plan & Text line 10, **Insert** The Studland No Anchoring Zone is now marked with yellow marker buoys, details PHC LNTM 08/24 https://www.phc.co.uk/wp-

content/uploads/2024/03/2024-08-Studland-Bay-Voluntary-No-Anchoring-Zone.pdf RE 3/24 Insert depth, 2·1 in 50° 39′·54N 1° 55′·19W.

NM 2274/24

Insert depth, 0·3 in 50° 40′·70N 1° 55′·84W and extend 2m to enclose. NM 2274/24

p53 POOLE HARBOUR AND ENTRANCE, Plan

Replace unlit G bn with lit bn Bn buoy Fl.G.4s in 50° 42′.49N E 1° 59′.04W. NM 2752/24

p56 **NEEDLES CHANNEL,** Text

Insert in Col 4. The sandbank NE of Hurst Point is rapidly changing. Small craft are advised to give Hurst Point a wide berth.

ILNW 96/2023

p57 **YARMOUTH,** Text

Entrance; Insert, Line 13. Some of the visitors' buoys N of the breakwater are in shallower water than shown on the chart and in the Harbour Guide. Parts of the western end of the middle trot (9-12m LOA) have only about 0.5m at CD. Deepest water is to the east. If in doubt, call the HM.

RE August 2023

p69 LANGSTONE HARBOUR, Plan

Insert Con G buoy LFI.G *Mulberry* in 50° 47′·82N., 1° 01′·64W. NM 3332/23
Insert BRB Isolated Danger buoy FI.2s in 50° 48′·11N 1° 01′·51W which is close NE of Turbine. NM4696/23

p72 CHICHESTER HARBOUR (EAST), Plan

Insert drying heigt, 0·2, and extend 0m low water line Seto enclose in 50° 48′·16N., 0° 50′·60W . NM2412/24

p75 **NEWHAVEN** Plan

Amend light at LT HO from Oc(2)10s17m12M to, lso.4s17m12M in 50° 46′·55N 0° 03′·51E NM 882/23

p76 **EASTBOURNE – SOVEREIGN HARBOUR,** Plan Delete G buoy Fl.G.3s in 50° 47′·37N 0° 20′·21E.

NM 659/23

p77 DOVER HARBOUR, Plan

Delete pier-head light Fl(2)R.5s in 51° 07′·50 N 1° 20′·28 E. NM1085/23

England East Coast

p83 **THAMES ESTUARY PASSAGES** Plan **Move** Long **Sand Head** N card buoy, VQ, Bell to 51° 48'·37N 01° 38'·16E

Insert new East Card buoy, BYB, East Long Sand Head, Q(3) 10s, AIS, in 51° 48'·12N 1° 39'·39E TH 5/2004

p88 **RIVER THAMES,** Tex, Col 4 Line 20, **Limehouse Dock Marina** Replace text "No visitors with":

Visitor berths are usually available. Contact the marina office 0207 308 9930 well before arrival, when you reach Limehouse call again on VHF 80. Berthing normally on pontoon H, max draft 2m. This is the headquarters of the CA, with its club house, library overlooks the basin and welcomes visitors.

p89 RIVER THAMES, Halfway Reach, Plan

Delete BY N cardinal Lt bn Q.5m2M in 51°30′·81N 0°08′·06E ILNW 149/24

p91 RIVER CROUCH, COLNE & BLACKWATER Approaches

Insert drying height, 0·1, enclosed by 0m low water line in 51° 36′·71N 1° 09′·29E, and drying height 0·3, enclosed by 0m low water line in 1° 09′·45E.

Ed from NM3363/24

p 92 RIVERS CROUCH AND ROACH, Plan

Insert Y Sph buoy Ray Sand North in 51° 40′-81N 1° 00′-57E.

Y Sph buoy Ray Sand in 51° 39′·84N 1° 00′·57E. **Delete** W sph buoy Ray Sand 51° 39′·08N., 0° 59′·28E. RW buoy Ray Sand Middle in 51° 40′·00N., 0° 59′·00E. RW buoy Ray Sand North in 51° 40′·70N., 0° 59′·50E

p 96 WALTON BACKWATERS, Text

Col4, line5: **Replace** "Channel on plan." with "After about 1M, at the unlit N card buoy, the deep water channel curves to the West and Titchmarsh Marina. Or to the South, at HW -0300, for draft 1.6m, a narrow buoyed channel leads to WFYC where a quay can be used HW -0200 to HW. "

p 97 WALTON BACKWATERS, Inset Plan

Insert N Card buoy (unlit) in 51° 51'-85 N 1° 16'-20 E.

Ed

p99 RIVER ORWELL, Text

Insert at end of first paragraph: Advisable to maintain a listening watch on Orwell Navigation Service VHF 68. **Pin Mill** Insert in line 6: For visitor's mooring Harry King (boatyard) 01473 780258, or 07867 640650.

Facilities: no fuel.

p99 IPSWICH, Text col 4,

Fox's Marina: Amend "Enter channel S of No.12 buoy" to "Enter channel N of No.12 buoy".

Marina HN

Neptune and **Ipswich Haven** Marinas are now one organisation **Ipswich Beacon Marina**, Tel 01473 236644. VHF 80. Facilities unchanged.

Insert at end of 1st paragraph:

Long vessels extending well into the main channel may be berthed at Ipswich Power Station berth, near S end of Cliff Quay. Leisure craft are requested to pass well clear.

p100 RIVER DEBEN, Plan

Entrance Bar, Buoy positions based on TH survey of April 2024 are as follows:

G Mid Knot in 51° 58′·65N 1° 23′·78E R West Knoll in 51° 58′·79N 1° 23′·69E G Deben in 51° 58′·91N 1° 23′·58E

R Knoll Spit in 51° 58'-95N 1° 23'-53E TH/ILNW

p101 ORFORD HAVEN, Plan

Entrance Bar, Buoy positions based on TH survey of April 2024 are as follows:

Orford Haven RWspher in 52°02′·00N 01°28′·20E Oxley R can in 52°02′·07N 01°27′·70E

Weir G con in 52°02'·24N 01°27'·57E TH/ILNW

p102 ORFORD HAVEN, Text

Col2 Facilities line 4: Delete "Orford garage (½M) or"

Ed

p103 **LOWESTOFT**, Text

Col 1 line 4 Insert Two white, lit, rectangular marks have been built in 52°27'·64N 1°44'·61E Fl.Y 5s and In 52°27'·72N 1°45'·82E Fl.Y 2·5s HM.

p104 NORFOLK BROADS, Text

Insert Mariners are advised that Haven Bridge is currently not able to lift due to technical issues.

Peel Ports 38/2023

p105 BLAKENEY MARBOUR, Plan

Amend light on Fairway Marker buoy to L.Fl.10s in 52° 59'-23 N 0° 58'-54' E

Replace existing No.2,4,6,5,7,8 and Insert
No. 1 stb buoy Fl.G 2s in 52° 58.91 N 0° 58.4 E
No.3 stb buoy Fl.G 2.5s in 52° 58'.86 N 0° 58'.26 E
No. 5 stb buoy Fl.G 5s in 52° 58'.87 N 0° 57'.98 E
No. 9 stb buoy Fl.G 2.5s in 52° 58'.78 N 0° 57'.53 E

No.10 port buoy QFI.R in 52° 58'-73 N 0° 57'-55 E

BHA Mar 24

p107 APPROACHES TO KING'LYNN AND WISBEECH

Plan. **Delete** spherical Y Buoy FI(5)Y.20s in 52° 56′·50N 0° 19′·10E. NM1069/24

p109 RIVER HUMBER APPROACHES, Plan

Insert conical Y buoy FI(5)Y.20s in 53° 33′·60 N 0° 09′·31 E. NM3675/24

p109 RIVER HUMBER ENTRENCE, Plan

Insert depth 2.6 in 53° 35′.95N 0° 00′.30E.

NM1353/24

p114 **SEAHAM**, Plan

Amend light at North Pier head to FI(4)G.10s10M in 54° 50′·26N 1° 19′·25W. NM800/24

p114 **SUNDERLAND,** Plan

Delete R can buoy in 54°56'.31N 1°20'.86W

ILNW 130/24

p114 RIVER TYNE, Text

St Peter's Marina: Tel Insert 07498 863198.

VHF replace 37,80 with 13. Marina 4/2024

p114 **BLYTH,** Text

Approach Line 5,

Delete There are Ldg diamond topmarks. **Insert** There is a light DirWRG.4s10M in 55° 07′·44N 1° 29′·84W. Enter on the narrow W sector on 324°.

p115 BLYTH, Plan

Delete leading lights F.Bu in 55°07′·50N 1°29′·91W, and 55°07′·42N 1°29′·82W and associate leading line 324°and legend 324°.

Insert Lt Dir.WRG.4s14m10M with assoc Lt sector 322°-Iso.G-324°-AI.GW-325°-Iso.W-327°-AI.RW-328°-Iso.R-330° in 55° 07'·44N 1°29'·84W. ILNW 392/23

p117 BERWICK, Plan

Insert light Fl.G.3s on No.3 G con buoy in 55° 45′·73N 1° 60′·00W NM 2023/24

East and North Scotland Coasts

p119 BERWICK TO ARBROTH, Passage Lights Isle of May, amend Range from 22M to 18M. NL09

p123 RIVER TAY Continuation, Plan Insert E card buoy VQ(3)5s in 56° 27′-60N 2° 57′-16W and delete legend 2Bns close W of above NM247/23

p124 MONTROSE, continuation, Plan Amend light-beacon to, F.G.2M in 56° 42′-19N 2° 27′ 75W. NM2965/24

p125 PETERHEAD Plan

Replace depth 2·4, with depth 1·6, and extend 2m contour E to enclose in 57° 30′.51N 1° 46′.24W.p1pp NM3443/22

p127 BUCKIE, Plan

Amend light to, Fl.G.2s5m4M in 57° 40′-81N 2° 57′.65W. NM3732/23

Amend light to, Fl.R.2s6m4M in 57° 40′-83N 2° 57′.71W. NM776/24

Insert minor R Lt in 57°40′-82N 2°57′-58W G Lt in 57°40'.80N 2°57'.57W ILNW 43/24

p128 BURGHEAD, Plan

Amend range of light to 2M, in 57° 42′-11N 3° 29′.93W and range of light to 3M, in 57° 42′.08N 3° 30′·03W. NM4582/23

Insert new pier lights:

Fl.R.4s 4m2M in 57° 40'-82N 2° 57'-58W Fl.G.4s 3m2M in 57°40'-80 N 2° 57'-57W NM536/24

p128 CALEDONIAN CANAL, Text Amend Tel Clachnarry Sea Lock to 01463 725512, or 07920 237331.

p135 SHETLAND, Fair Isle, Plan

Amend range of North Skroo light in 59° 33'.13N 1°36°.59W, from 22M to 18M. NL 14/22

Scotland West Coast

p145 ISLE OF ORNSAY, Plan

Insert unlit Y bns in 57° 08′-65N 5° 47′-95W and 57° 08′ 68N 5° 47′ 52W with underground electric NM457/24 cable between them.

p157 STORNOWAY, Plan

Delete depth 6.8m and surrounding dotted circle in 58° 11′-86N 6° 22′-80W. NM4143/23

p157 STORNOWAY, Lewis: Plan.

Insert Deep Water Terminal, adjoining existing shore to N of Armish Heights, approximate position: NW, adjoining shore, in 58° 11'-80N 6° 23'-30W NE corner in 58° 11'.80N 6° 23'.07W 58° 11'.70N 6° 23'.02W SE corner in SW, adjoining shore, in 58° 11'.80N 6° 23'.20W Main berth alongside NE to SE edge.

These figures were produced by Hon Ed from the NM Much better see the block Admiralty NM Week 23: number 2547.

Insert

G lateral buoy, Fl.G.4s in 58° 11'.95N 6° 22'.73W R lateral buoy, Fl.R 4s in 58° 11'-72N 6° 22'-60W R lateral buoy, Fl.R 2s in 58° 11′ · 64N 6° 22′ · 77W Stornoway 3/2024

p161 CAMBLETOWN, Plan

Insert depth: 0.8m in 55°25'.88N 5°33'.60W and extend 2m depth to enclose. ILNW 177/22

p162 ARDRISHAIG, Text

Col2 Entrance: After pontoon insert 'marked at its E end by It FI.G.3s in 56° 00′-75N., 5° 26′-66W '

NM3602/24

p164 TROON, Text

Depths shown within Troon Harbour are subject to siltation and liable to change. For the latest information, consult HM. ILNW 86/24

p164 LOCH RYAN, Plan11

Delete light Bns

Oc.G.6s No 1 in 54° 56′-68N, 5° 01′-32W. F.G.3s No 5 in 54° 55′.09N., 5° 01′.86W. No 3 in 54° 55′·88N., 5° 01′·59W. NM1005/24

p164 LOCH RYAN, Text, cols 3 and 4

Stranraer Marina:- Delete:- three G Lt bns mark the W side of the channel leading into Stranraer Hbr and marina.

Inserts:- from the Spit G con buoy Fl.G.6s steer for a point slightly NW of Stranraer from where entry can be made to the marina.

The Wig:-Delete:- passing midway between Spit G con buoy Fl.G.6s and No.1 bn Oc.G.6s.

Insert:- turning S 0.3M S of Spit G con buoy Fl.G.6s., then make good a suitable course to the anchorage.

Ed

England West Coast and Wales

p173 FLEETWOOD HARBOUR, Plan

Amend light characteristics to, Iso.4s in 53° 55′·59N 3° 00′·46W and light to, Iso.2s in 53° 55′·72N 3° 00′·55W. NB No colour means that the lights are now both White

p175 LIVERPOOL, RIVER MERSEY Plan

Insert Lt on quay 2F.R(vert) in 53° 24′·74N 3° 00′·18W. NM 937/2024

p180 HOLYHEAD, Plan

Amend fog signal Siren 20s to Horn 20s at Lt in 53°19′.85N 4°37′.16W ILNW 231/23

p183 FISHGUARD, Text

Tel/VHF Old Harbour. **Amend** HM 01348 873389 to HM office 01834 842717.

p186 MILFORD HAVEN ENTRANCE, Plan

Insert AIS at Mid Channel Rocks W Card light buoy in 51° 40′·17N 5° 10′·10W NM462/2024

p187 MILFORD HAVEN, Central Section

Amend Outfall light-buoy to, VQ in 51° 41′·75N 4° 59′·74W NM 4970/22

p188 MILFORD HAVEN TO LAND'S END, Passage

Seven Stones LtV Amend Fog Signal from Horn (3) 60s to Horn(1)30s TH16/24

p188 NAVIGATION IN THE BRISTOL CHANNEL

Nash Point: Amend range, white to 19M and red to 14M TH41/22 Trevose Head Amend range to 18M Ad Lt List 10/23

p195 PADSTOW, Plan

Move G lighted buoy Fl.G.5s Doom Bar from 50° 33'·59 N 4° 56'·23 W to 50° 33'·51N 4° 56'·31 W Move R lighted buoy LFl.R.10s Daymer from 50° 33'·50 N 4° 56'·39 W to 50° 33'·49N 4° 56'·20 W Move G lighted buoy Fl.G.10s Gun Pt from 50° 33'·26N 4° 56'·24 W to 50° 33'·27 N 4° 56.25 W Insert Wreck buoy symbol Fl(2).G.5s Antoinette in 50°33'·81 N 4° 56'·17' W and Delete existing wreck buoy Fl(2).10s close SW. ILNW11/2023 Amend light-buoy to, Fl(2)G.5s Antoinette in 50° 33′·79N., 4° 56′·14W NM

Ireland

p201 VALENTIA, Plan

Insert W card buoy YBY Q(9)15s in 51° 56′·71N 10° 17′·49W and delete isolated danger mark Fl(2)6s close by. NM2649/23

p211 CORK HARBOUR, Plan

Insert light 2F.R(vert)3m1M in 51° 50′·12N 8° 18′·26W. NM1658/24

p212 CORK TO TUSKAR ROCK, Passage Lights Tuskar Rock

Amend range of Lt Q(2)7·5s33m24M to 18M ILNW 384/22

p214 WATERFORD HARBOUR, Plan

Insert spherical Y buoys Fl.Y.6s in 52° 15'·55N 7° 02'·07W and in 52° 16'·00N 6° 58'·72W. NM547/24 Move Lt Fl(3)R.10s6m4M from 52°08'·98N 6°59'·40W to 52°08'·99N 6°59'·39W ILNW 323/23

p215 WATERFORD, Text

Waterford City Marina will be closed to visitors until 2025. Works in progress. City Counci

p215 IRELAND - EAST COAST, Passsage Lights, Kish Bank Amend range of light from 21M to 18M. Irish Lights 03/2024

p218 DUBLIN BAY, Plan

Move No 1 G con buoy to 53° 20′·27N 6° 05′·26W NM3016/23

Delete Y buoy with top mark, Q(5)20s and *AIS* in 53° 21′·32N 6° 05′·37W. NM1036/24 p218 **BELFAST,** Plan

Amend light to, Fl.Y jn 54° 36′·34N 5° 54′·90W.

Delete pier light 2F.G (vert) in 54° 36′·27N 5° 55′·18W

NM1906/2023

p219 HOWTH, Plan

Amend range of Lt Fl.G.3s6M to 3M in 53°23'.53N 6°04'.08W ILNW 291/23

p231BURTONPORT, Text

Col 1 line 7. After 081487 6482 **insert** or 0873 354831, main office 0868 310121. Ed 9/23

p240 CASHLA BAY, Plan

Insert depth 0.8 m in 53° 16′.50N., 9° 33′.87W and extend 2m contour SW to enclose . NM3589/23 Insert con G buoy Fl.G.2s in 53° 15′.84N 9° 02′.43W NM436/24

p240 GALWAY, Plan-

Insert G con Lt buoy with topmark Fairway Buoy No 3 Fl.G.2s in 53°15′·84N 9°02′·43W ILNW 35/24

p241 KILRONAN HARBOUR, Text

Anchorage Insert: Easy access; keep clear of ferries.Ed

p243 **DINGLE HARBOUR**, Plan

Amend range of Lt DirOc.WRG.4s13m2M to 3M in 52°08'·33N 10°16'·52W ILNW 414/22

Belgium

p245 NIEUPOORT, Plan

Amend range of light at pierheads to 11M in 1° 09′·35N 2° 43′·00E and 51° 09′·42N 2° 43′·08E.

NM1475/24

p245 **OOSTENDE, Plan**

Amend Range of light in 51°14'·19N 2°55'·79E from 27M to 22M. NM 4828/23

Amend Range of light in 51°13'-80N 2°55'-89E from 4M to 18M

Amend Height and Range of light in 51°13'-63N 2°56'-10E from 46m 4M respectively to 50M and 18M. NM514/24

Amend range of light at pierheads to, 11M, in 51° 09′·35N., 2° 43′·00E and 51° 09′·42N., 2° 43′·08E.

p246 ZEEBRUGGE,Plan

Delete Lt F.G in 51°20′-39N 3°11′-74E ILNW 234/23

Netherlands

p255 **STANDING MAST ROUTE**, Text

Col 1, line 4: **INSERT** "local time" after "0200". Col 1, At end of 1st paragraph insert "Amsterdam rail bridge not operating from 1st Oct 2023 until 31st May 2024 for vessels with more than 6.25 m above normal canal level. Use the Haarlem route instead."

p257 **APPROACHES TO THE WESTERSCHELDE,** Plan **Insert** R can Lt buoy SS 2 Q.R in 51°25′·50N 3°37′·92E. **Delete** R spar buoy SS 2 close to NW Replace G starboard spar buoy SS 5 with Y special pillar buoy ARV 5 in 51°24′·71 N 3°38′·04E

Delete G starboard spar buoy SS 3 in 51°25′·04N 3°37′·30E.

Delete R can Lt buoy SS 4 Q.R in 51°25′·23N 3°37′·82E ILNW 304/22

p259 ENTRANCE TO THE OOTTERSCHELDE, Plan Replace light and designation of bn WG4 to Fl(5)Y20s OS11 in 51° 38'·62N 3° 28'·88E . NM514/24

Approaches to the Baltic

p276 **ROUTES and PORTS**, Table

Replace tel no +47 51517000.with +47 800 88 870

RE 4/24

p281 INTRODUCTION, Fuel

Lines 4 – 6 . **Replace** "Diesel sold the Baltic" by "All diesel sold for marine use will contain some bio-diesel". RE 1/24

p293 EGERSUND, Plan

Ruskodden light sectors changed: From offshore N sector G sector changed to R. White sector unchanged. R sector changes to G. ww.norgeskart.no

p302 KOBENHAVEN, Text

Approach Yachts enter Lynetteløbet as shown on the planac 2024 is shut and the channel markers removed. Pleasure craft now have an entry route into Copenhagen port to the South of the main Kronløbet channel marked by green posts

p304 LAGUNEN YACHT HARBOUR, Plan

Latitude scale. Insert 12° before 56′·0 RE11/23

p306 WARNEMUNDE Plan

Insert E card buoy, BYB, in 54° 11′·05N 12° 05′·26E. NM2971/23

France North Coast, and Channel Islands

p315 FRANCE - NORTH COAST, Text

Formalities Insert From June 1st France has permitted designated marinas to complete the Entry/Exit process for third country nationals arriving in via France. For full details a list of marinas **Click Here.**

p315 **FRANCE – NORTH COAST,** Distance Table **Nab Tower to Dieppe** Replace 65 by 93. R.M/06/24

p316 DUNKERQUE, Plan

Move G con buoy Q.G *DW29* to 51° 03′·81N 2°20′·20E. NM3541/23 **Amend** light to, Fl(3)G.12s11m6M in 51° 03′·25N 2° 21′·20E. NM 2367/24

p317 **CALAIS TO LE HAVRE,** Passage Lights

Replace Cap de Alprech with

Le Toucet 1196

Fl(2)10s54m25M

RE

p320 ST-VALERY-EN-CAUX, Plan

Amend height of stb pierhead light from 13m to 12m. NMWk43Lt List

p321 **FECAMP**, Plan

Amend light to Fl(2) 6s 15m 12M at Jetée Nord, Head in 49° 45′.92 N 0° 21′.80 E NM 4692/23

p323 **OUISTREHAM**, Text

There is now **new berthing** in the avant-port inshore of the new waiting pontoon. RE 6/24

p327 BARFLEUR, Plan

Insert lit mooring buoy sym. Fl.Y.4s in 49°40′·50N 1°15′·68W ILNW 83/24p327p

p327 **CHERBOURG**, Text

Berthing line 5, pontoons: **Delete** N from list of pontoons. HM 5/24

p328 CHERBOURG, Plan

Delete light Q.16m13M in 49°39′·06N 1°36′·01W ILNW 471/22

p329 **PASSAGE LIGHTS**, Guernsey

Platte Fougère Delete Racon(P) ILNW 354/23 Insert AIS NM Lights List 15/24

p333 **BEAUCETTE** Plan

Platte Fougère Insert AIS to characteristics of light at north end of drying rock in 48° 30'-83N 2° 29'-14W ILNW155/24

p337 GRANVILLE, Plan

Delete fog signal Horn(2)40s at Lt FI(2)R.6s5M in 48°49′·89N 1°35′·89W ILNW 181/24

p338 ST MALO APPROACHES, Plan

Insert rock which covers / uncovers sym. in 48°39′·48N 2°01′·71W ILNW204/23

Delete unlit R buoy with top mark No4 Bell in 48° 40′·24N 2° 07′·20W NM4444/23

Delete R can buoy No 6 in 48°40′·26N 2°06′·13W

Amend Light of pillar buoy No 2 from No 2 from Fl.R.4s to Fl.R.2·5s in 48°40′·24N 2°07′·35W.

ILNW 356/23

p341RIVER RANCE, Text

Col 1: Plouër Marina. **Amend** "10 visitors' berths" to "visitors usually berth on B pontoon, best to call HM". **Delete** "two waiting pontoons outside marina". Ed

p341 ST-CAST-LE-GUIDO, Text

Col 2: Approach At end, insert "there are numerous fishing floats in the approaches, extreme caution advised at night."

p341 ST CAST, Plan,

Longitude Scale. **Amend** 15.5' to 14'.5 .

Ed

p341 DAHOUET, Plan,

Remove the drying rocky area on E side of marina. **Insert** a short pontoon (D-2) close to the pier in the ENE area.

RE/Marina plan

p345 RIVIERE DE TREGUIER, Plan

Insert rock awash sym in 48°52'.05N 3°09'.21W. Delete fog signal, Whis, at light-buoy, Basse Crublent, in 48° 54′·28N 3° 11′·15W. NM3951/23 Move R can Lt buoy Le Corbeau from 48°53'-37N 3°10'.25W to 48°53'.29N 3°10'.11W Move G con Lt buoy Pierre à l'Anglais from 48°53'.20N 3°10'.43W to 48°53'.30N 3°10'.44W Insert 1.0m in 48°52'.58N 3°08'.55W ILNW 325/23 Replace depth: 1.9m with drying rock sym in 48°52'.50N 3°08'.18W ILNW 325/23 Move R buoy Q.R Basse Crublent to: 48° 54'.21N 3° 11′-24W. NM941/2024 **Delete** House in (a) 48° 51′.00N. 3° 07′.11W. Delete leading line, pecked line, joining: (a) above 48° 51′.55N 3° 07′.88W RE FN 41/46/23

p344/5 TRIEUX RIVER, LEZARDRIEUX, Text

Berthing, p345/Col1: line 20, Delete "visitor's buoys"
Col 2, line 5 Amend 2·2m to 1·6m, Insert Owing to silting contact Harbour Master. RE: 30 July 2024

p348 LANNION RIVER, Plan

Locquémeau. **Amend** Range W sector to 8, all other characteristics unchanged, in 48°43'·28 N 3°34'·11 W.

BA Lights Wk8/24

p352 ILE DE BATZ Plan

Delete BYB E card Bn in 48°43'.75N 3°59'.42W ILNW 34/23)

Replace BY N cardinal Bn Tr with W Bn Tr in

48°44′·10N 3°59′·70W ILNW 24/24

France, West Coast

p357 FRANCE - WEST COAST, Text

Customs and Immigration: Insert From June 1st France has permitted designated marinas to complete the Entry/Exit process for third country nationals arriving in via France. For full details and a list of Ed marinas Click Here.

p366 **CONCARNEAU**, Text

Facilities Insert Fuel

RE

p378 LES SABLES D'OLONNE, Plan

Insert sectors at light, Iso.4s33m16M in: 46° 29′.58N., 1° 46′·23W as follows W 25°- 40° (15°) NM4008/23

Northwest Spain

p388 HONDARRIBIA AND HENAYE, Plan

Insert Y special spar buoy in 43°22′·02N 1°47′·05W

ILNW 43/23

p391 PUERODE BILBAO, Plan

Amend Lt: FI(2)G.8s1M to Oc(2)G.7s1M in 43°21'.80N

3°04'.65W

Amend Lt: FI(3)G.10s3M to FI(4)G.12s3M in

43°20'.79N 3°01'.91W

Amend Lt: FI(4)G.12s to FI.G.4s in 43°20'-59N

3°01'.93W

Amend Lt: FI(3)G.10s to Oc(2)G.7s in 43°19'.81N

3°01'.78W

Amend Lt: FI(2+1)G.10s to FI(4)Y.12s in 43°19'.93N

3°01'.60W. ILNW 53/23

Work is complete on reclaiming land at the E end of Dique de Zierbena

Insert Lt Oc.G.6s1M in 43°21'-41N 3°02'-81W. Delete Lt Fl.G.5s12m1M close W. II NW 182/24

p394 PUERTO DE RIBADESELLA

The depth to the NW of the marina is no longer maintained. Delete lgd 1.5m centred on 43°27'.89N 5°03'.75W ILNW 19/23

p400 A CORUÑA/LA CORUÑA, Text

Marina Carunnna: Amend tel to 881 920 482. RE

p404 RIA DE AROUSA, Plan

Delete pillar buoy Fl.Y. 5s3M in 42° 35′-50N

8° 54′-63W. NM 2795/24

p407 **RÍA DE VIGO,** Plan

Replace YBY W card Lt buoy VQ(9)10s with BY N card pillar Lt buoy Q in 42°09'.29N 8° 53'.21W

ILNW 20/24

Text Col3 Line 2: Replace Las Serralleiras W card with Las Serralleiras N card. Ed

Portugal, Southwest Spain, and Gibraltar

p 413 LISBOA APPROACHES, Plan

Move G pillar Lt buoy No 5 Fl.G.4s from 38°40'.43N 9°17'.66W to 38°40'.47N 9°17'.77W ILNW 339/23

p415 SINES Marina

This Marina has now been reopened. RE

p416 PORTIMAO Plan

Delete anchorage sym in 37°07′·75N 8°31′·63W ILNW 170/23

p417 VILAMOURA, Plan

Amend range of Lt Fl.5s17m19M to 12M in 37°04′·47N 8°07′·38W ILNW 26/23

p418 VILA LA REAL DE SANTO ANTONIO, Plan

Insert Lt: FI(2)R.5s in 37°12'·10N 7°24'·88W FI(2)G.5s in 37°12'·14N 7°24'·88W. ILNW 18/24

p419 ISLA CRISTNA

Insert Add topmark to R pillar Lt buoy with topmark No 6 Q(3)R.9s4M in 37°11'.88N 7°19'.77W

ILNW 21/24

p421 BAHIA DE CADIZ, Plan

Move R buoy Bajo El Quemado Fl(2)R.9s, from: 36° 35′.99N 6° 23′.89W to: 36° 35′.99N 6° 23′.97W. NM2863/24

TIDE TABLE BOOKLET

p1 Move ((Devenport) currently following RE 2/24

Portsmouth so that it follows Plymouth.

p96 BREST - TIDAL COEFFICIENTS

Amend 2023 to 2024 **ILNW**